

| Cars/bus



| Cars/Bus | Avant | Arrière | Essieu | Roulement intérieur Réf. SNR | Roulement | Roulement extérieur Réf. SNR | Roulement |
|------------------------|-------|---------|--------|------------------------------------|-----------|------------------------------------|-----------|
| IVECO | | | | | | | |
| 2480.12 | | • --- | | HDB003 | 30221.A | HDB016 | 32024.A |
| 370.10-24 | • | --- | | HDB003 | 30221.A | HDB016 | 32024.A |
| 370.10-25 | • | --- | | --- | --- | HDB009 | 32310.A |
| 370.12-24 | • | --- | | --- | --- | HDB009 | 32310.A |
| 370.12-25 | • | --- | | --- | --- | HDB009 | 32310.A |
| 370.12-25L | • | --- | | --- | --- | HDB009 | 32310.A |
| 370.12-30 | • | --- | | --- | --- | HDB009 | 32310.A |
| 370.12-35 | • | --- | | --- | --- | HDB009 | 32310.A |
| 370S.10-24 | • | --- | | --- | --- | HDB009 | 32310.A |
| 370S.12-24 | • | --- | | --- | --- | HDB009 | 32310.A |
| 370S.12-25L | • | --- | | --- | --- | HDB009 | 32310.A |
| 370S.12-30 | • | --- | | --- | --- | HDB009 | 32310.A |
| 370S.12-35 | • | --- | | --- | --- | HDB009 | 32310.A |
| 380.12-35 Euroclass | • | --- | | --- | --- | HDB009 | 32310.A |
| 380.12-38 HD | • | --- | | --- | --- | HDB009 | 32310.A |
| 4480-18 | | • --- | | HDB003 | 30221.A | HDB016 | 32024.A |
| 470.10-20 | | • --- | | HDB008 | 33021.A | --- | --- |
| 470.12-20 | | • --- | | HDB008 | 33021.A | --- | --- |
| 570.10-20 | | • --- | | HDB008 | 33021.A | --- | --- |
| 570.12-20 | | • --- | | HDB008 | 33021.A | --- | --- |
| 670.12-20 | | • --- | | HDB008 | 33021.A | --- | --- |
| Citelis | • | R175 | | HDS001 | HUR040-10 | --- | --- |
| Euroclass 380.10-29, | • | --- | | --- | --- | HDB009 | 32310.A |
| Euroclass 380.12-29 | • | --- | | --- | --- | HDB009 | 32310.A |
| Eurotech 370SE-27/29 | • | --- | | --- | --- | HDB009 | 32310.A |
| Eurotech 370SE-35 | • | --- | | --- | --- | HDB009 | 32310.A |
| I-Effeuno 671.22-24 | | • --- | | HDB003 | 30221.A | HDB016 | 32024.A |
| S-Effeuno 571.10-20 | | • --- | | HDB003 | 30221.A | HDB016 | 32024.A |
| S-Effeuno 571.12-20 | | • --- | | HDB003 | 30221.A | HDB016 | 32024.A |
| Turbocity-I 3480.18-29 | | • --- | | HDB003 | 30221.A | HDB016 | 32024.A |

| | | | | | | |
|---------------------------------|---|-----|--------|---------|--------|---------|
| Turbocity-I 3480.18-29 | • | --- | --- | --- | HDB009 | 32310.A |
| Turbocity-I 3480.18-29 | • | --- | HDB003 | 30221.A | HDB016 | 32024.A |
| Turbocity-I 680.12-26 | • | --- | --- | --- | HDB009 | 32310.A |
| | • | --- | HDB003 | 30221.A | HDB016 | 32024.A |
| Turbocity-S 580.10-21 | • | --- | --- | --- | HDB009 | 32310.A |
| | • | --- | HDB003 | 30221.A | HDB016 | 32024.A |
| Turbocity-S 580.12-21 | • | --- | --- | --- | HDB009 | 32310.A |
| | • | --- | HDB003 | 30221.A | HDB016 | 32024.A |
| Turbocity-S 580E.12-22 | • | --- | --- | --- | HDB009 | 32310.A |
| | • | --- | HDB003 | 30221.A | HDB016 | 32024.A |
| Turbocity-SR 590E.12-22 | • | --- | --- | --- | HDB009 | 32310.A |
| Turbocity-U 480.10-21 | • | --- | HDB003 | 30221.A | HDB016 | 32024.A |
| Turbocity-U 480.10-21, | • | --- | --- | --- | HDB009 | 32310.A |
| Turbocity-U 480.12-21 | • | --- | --- | --- | HDB009 | 32310.A |
| | • | --- | HDB003 | 30221.A | HDB016 | 32024.A |
| Turbocity-U 480E.10-2 | • | --- | HDB003 | 30221.A | HDB016 | 32024.A |
| Turbocity-U 480E.10-22 T | • | --- | --- | --- | HDB009 | 32310.A |
| Turbocity-U 480E.12-22 | • | --- | --- | --- | HDB009 | 32310.A |
| | • | --- | HDB003 | 30221.A | HDB016 | 32024.A |
| Turbocity-U 480E.12-26 | • | --- | --- | --- | HDB009 | 32310.A |
| | • | --- | HDB003 | 30221.A | HDB016 | 32024.A |
| Turbocity-UR 490.10-22 | • | --- | --- | --- | HDB009 | 32310.A |
| Turbocity-UR 490.12-22 | • | --- | --- | --- | HDB009 | 32310.A |
| Turbocity-UR 490E.10-22 | • | --- | --- | --- | HDB009 | 32310.A |
| Turbocity-UR 490E.12-22 | • | --- | --- | --- | HDB009 | 32310.A |
| U Effeuno 471.10-20 | • | --- | HDB003 | 30221.A | HDB016 | 32024.A |
| U Effeuno 471.12-20 | • | --- | HDB003 | 30221.A | HDB016 | 32024.A |

MAN

| | | | | | | |
|--------------------------------|---|-----------|--------|---------|--------|---------|
| 292 (Type 880) | • | V7-70SL | --- | --- | HDB009 | 32310.A |
| | • | V7-75SL | --- | --- | HDB009 | 32310.A |
| | • | H07-1080 | HDB008 | 33021.A | HDB001 | 32019.A |
| | • | H09-1180 | HDB008 | 33021.A | HDB001 | 32019.A |
| 292/332/362H (Type 882) | • | V7-70SL | --- | --- | HDB009 | 32310.A |
| | • | V7-75SL | --- | --- | HDB009 | 32310.A |
| | • | H07-1080 | HDB008 | 33021.A | HDB001 | 32019.A |
| | • | H09-1180 | HDB008 | 33021.A | HDB001 | 32019.A |
| EL 202 (Type A12) | • | V9-65L | --- | --- | HDB009 | 32310.A |
| | • | HONL-1180 | --- | --- | HDB001 | 32019.A |
| NL 202 (Type 895) | • | V9-65L | --- | --- | HDB009 | 32310.A |

| | | | | | | |
|------------------------------------|---|--------------|--------|---------|--------|---------|
| | • | HOLN-1180 | HDB008 | 33021.A | HDB001 | 32019.A |
| NL 202 F (Type 898) | | | | | | |
| | • | V9-65L | --- | --- | HDB009 | 32310.A |
| | • | HONL-1180 | HDB008 | 33021.A | HDB001 | 32019.A |
| NM-152, MIDI-BUS (Type A05) | | | | | | |
| | • | V9-65L | --- | --- | HDB009 | 32310.A |
| SG 242/282H (Type 795) | | | | | | |
| | • | H07-1080 | HDB008 | 33021.A | HDB001 | 32019.A |
| SG 242/292, 322 (Type 793) | | | | | | |
| | • | V7-70SL | --- | --- | HDB009 | 32310.A |
| | • | V7-75SL | --- | --- | HDB009 | 32310.A |
| | • | H07-11120 | --- | --- | HDB001 | 32019.A |
| | • | H07-10/11120 | --- | --- | HDB001 | 32019.A |
| | • | H07-1080 | --- | --- | HDB001 | 32019.A |
| | • | H07-11120 | --- | --- | HDB001 | 32019.A |
| | • | HOM7-1100 | --- | --- | HDB001 | 32019.A |
| | • | HOM7-1100 | --- | --- | HDB001 | 32019.A |
| SL 200 (Type 192) | | | | | | |
| | • | H07-1080 | HDB008 | 33021.A | HDB001 | 32019.A |
| SL 202 (Type 791) | | | | | | |
| | • | V7-70SL | --- | --- | HDB009 | 32310.A |
| | • | V7-75SL | --- | --- | HDB009 | 32310.A |
| | • | H07-1080 | HDB008 | 33021.A | HDB001 | 32019.A |
| | • | H09-1180 | HDB008 | 33021.A | HDB001 | 32019.A |
| SUE 240/280, (Type 789) | | | | | | |
| | • | H07-1080 | HDB008 | 33021.A | HDB001 | 32019.A |
| SUE 242 (Type 888) | | | | | | |
| | • | V7-70SL | --- | --- | HDB009 | 32310.A |
| | • | V7-75SL | --- | --- | HDB009 | 32310.A |
| | • | H07-1080 | HDB008 | 33021.A | HDB001 | 32019.A |
| SUE 242 (Type 888) | • | H09-1180 | HDB008 | 33021.A | HDB001 | 32019.A |

MERCEDES-BENZ

| | | | | | | |
|---------------|---|-------------|--------|---------|--------|---------|
| 309 D | | | | | | |
| | • | VL2/11D-3.8 | HDB011 | 33211.A | --- | --- |
| 309 D | | | | | | |
| | • | VO3/9DL-5 | HDB022 | 33213.A | HDB020 | 33208.A |
| O 817 | | | | | | |
| | • | HL4/35D-6.4 | --- | --- | HDB004 | 33113.A |
| O 1114 | | | | | | |
| | • | VL2/11D-3.8 | HDB011 | 33211.A | --- | --- |
| | • | HL4/29D-9.2 | HDB018 | 33117.A | --- | --- |
| O 1117 | | | | | | |
| | • | VL2/11D-3.8 | HDB011 | 33211.A | --- | --- |
| | • | HL4/29D-9.2 | HDB018 | 33117.A | --- | --- |
| O 1120 | | | | | | |
| | • | VL2/11D-3.8 | HDB011 | 33211.A | --- | --- |
| | • | HL4/29D-9.2 | HDB018 | 33117.A | --- | --- |
| O 1417 | | | | | | |
| | • | HH4/04D-12 | HDB013 | 33020.A | HDB018 | 33117.A |
| O 1617 | | | | | | |
| | • | VL4/2D-7 | --- | --- | HDB009 | 32310.A |
| | • | VO4/18DL-7 | --- | --- | HDB009 | 32310.A |
| O 1625 | | | | | | |
| | • | VL4/2D-7 | --- | --- | HDB009 | 32310.A |
| | • | VO4/18DL-7 | --- | --- | HDB009 | 32310.A |
| O 1628 | | | | | | |
| | • | VL4/2D-7 | --- | --- | HDB009 | 32310.A |
| | • | VO4/18DL-7 | --- | --- | HDB009 | 32310.A |
| O 301 | | | | | | |
| | • | VL2/11D-3.8 | HDB011 | 33211.A | --- | --- |
| | • | VO3/9DL-5 | HDB022 | 33213.A | HDB020 | 33208.A |
| O 303 | | | | | | |
| | • | VL2/11D-3.8 | HDB011 | 33211.A | --- | --- |

| | | | | | | |
|--------------|---|----------------|--------|---------|--------|---------|
| | • | VO3/9DL-5 | HDB022 | 33213.A | HDB020 | 33208.A |
| | • | VO4/13DL-7 | --- | --- | HDB009 | 32310.A |
| | • | HO4/01DL-10 | HDB013 | 33020.A | HDB018 | 33117.A |
| | • | HO4/10DL-10 | HDB002 | 33019.A | HDB010 | 33215.A |
| | • | HO4/10L-10 | HDB002 | 33019.A | HDB010 | 33215.A |
| | • | HO4/18DL-7.7 | HDB012 | 32216.A | --- | --- |
| | • | HO4/18L-7.7 | HDB012 | 32216.A | --- | --- |
| | • | HO5/8DL-10 | HDB002 | 33019.A | HDB010 | 33215.A |
| | • | HO5/8L-10 | HDB002 | 33019.A | HDB010 | 33215.A |
| O 305 | | | | | | |
| | • | VO4/11DL-7 | --- | --- | HDB009 | 32310.A |
| | • | HO7/8DL-10 | HDB008 | 33021.A | HDB001 | 32019.A |
| | • | NR7/4DL-10 | HDB008 | 33021.A | HDB001 | 32019.A |
| | • | NR7/5DL-10 | HDB008 | 33021.A | HDB001 | 32019.A |
| O 307 | | | | | | |
| | • | VO4/11DL-7 | --- | --- | HDB009 | 32310.A |
| | • | HO7/8DL-10 | HDB008 | 33021.A | HDB001 | 32019.A |
| O 309 | | | | | | |
| | • | VO3/9DL-5 | HDB022 | 33213.A | HDB020 | 33208.A |
| | • | VL2/11D-3.8 | HDB011 | 33211.A | --- | --- |
| O 402 | | | | | | |
| | • | VL2/11D-3.8 | HDB011 | 33211.A | --- | --- |
| | • | VO4/18DL-7 | --- | --- | HDB009 | 32310.A |
| | • | VO4/22DLE-6.6 | --- | --- | HDB009 | 32310.A |
| O 404 | | | | | | |
| | • | VL2/11D-3.8 | HDB011 | 33211.A | --- | --- |
| | • | VO4/21CLE-6.6 | --- | --- | HDB009 | 32310.A |
| | • | VO4/22DLE-6.6 | --- | --- | HDB009 | 32310.A |
| | • | VO4/35CLE-7.5 | --- | --- | HDB009 | 32310.A |
| | • | HO4/01DL-11.5 | HDB013 | 33020.A | HDB018 | 33117.A |
| | • | HO4/02CL-11.5 | HDB013 | 33020.A | HDB018 | 33117.A |
| | • | HO4/04DCL-11.5 | HDB013 | 33020.A | HDB018 | 33117.A |
| O 405 | | | | | | |
| | • | VL2/11D-3.8 | HDB011 | 33211.A | --- | --- |
| | • | VO4/18DL-7 | --- | --- | HDB009 | 32310.A |
| | • | VO4/22DLE-6.6 | --- | --- | HDB009 | 32310.A |
| | • | VO4/33DL-6.6 | --- | --- | HDB009 | 32310.A |
| | • | VO4/34DL-7 | --- | --- | HDB009 | 32310.A |
| | • | HO7/02DLM-10 | HDB008 | 33021.A | HDB001 | 32019.A |
| | • | HO7/10DL-11.5 | HDB008 | 33021.A | HDB001 | 32019.A |
| | • | HO7/9DL-10 | HDB008 | 33021.A | HDB001 | 32019.A |
| | • | NR7/4DL-10 | HDB008 | 33021.A | HDB001 | 32019.A |
| | • | NR7/5DL-10 | HDB008 | 33021.A | HDB001 | 32019.A |
| O 407 | | | | | | |
| | • | VL2/11D-3.8 | HDB011 | 33211.A | --- | --- |
| | • | VO4/18DL-7 | --- | --- | HDB009 | 32310.A |
| | • | VO4/22DLE-6.6 | --- | --- | HDB009 | 32310.A |
| | • | HO7/02DLM-10 | HDB008 | 33021.A | HDB001 | 32019.A |
| | • | HO7/10DL-11.5 | HDB008 | 33021.A | HDB001 | 32019.A |
| | • | HO7/9DL-10 | HDB008 | 33021.A | HDB001 | 32019.A |
| O 408 | | | | | | |
| | • | VL2/11D-3.8 | HDB011 | 33211.A | --- | --- |
| | • | VO4/18DL-7 | --- | --- | HDB009 | 32310.A |
| | • | VO4/22DLE-6.6 | --- | --- | HDB009 | 32310.A |
| | • | HO7/02DLM-10 | HDB008 | 33021.A | HDB001 | 32019.A |
| | • | HO7/10DL-11.5 | HDB008 | 33021.A | HDB001 | 32019.A |
| | • | HO7/9DL-10 | HDB008 | 33021.A | HDB001 | 32019.A |
| O 814 | | | | | | |
| | • | VL2/10D-3.5 | HDB011 | 33211.A | --- | --- |
| | • | HL4/30D-6.4 | --- | --- | HDB004 | 33113.A |
| | • | HL4/30DS-6.4 | --- | --- | HDB004 | 33113.A |
| | • | HL4/35D-6.4 | --- | --- | HDB004 | 33113.A |
| O 817 | | | | | | |

| | | | | | | |
|----------------------------|---|--------------|--------|---------|--------|---------|
| | • | VL2/10D-3.5 | HDB011 | 33211.A | --- | --- |
| | • | HL4/30D-6.4 | --- | --- | HDB004 | 33113.A |
| | • | HL4/30DS-6.4 | --- | --- | HDB004 | 33113.A |
| OH 1622 | | | | | | |
| | • | VL4/10D-7 | --- | --- | HDB009 | 32310.A |
| | • | VO4/18DL-7 | --- | --- | HDB009 | 32310.A |
| | • | HO4/01DL-10 | HDB013 | 33020.A | HDB018 | 33117.A |
| OH 1625 | | | | | | |
| | • | VL4/10D-7 | --- | --- | HDB009 | 32310.A |
| | • | VO4/18DL-7 | --- | --- | HDB009 | 32310.A |
| | • | HO4/01DL-10 | HDB013 | 33020.A | HDB018 | 33117.A |
| OH 1627 | | | | | | |
| | • | VL4/10D-7 | --- | --- | HDB009 | 32310.A |
| | • | VO4/18DL-7 | --- | --- | HDB009 | 32310.A |
| | • | HO4/01DL-10 | HDB013 | 33020.A | HDB018 | 33117.A |
| OH 1628 | | | | | | |
| | • | VL4/10D-7 | --- | --- | HDB009 | 32310.A |
| | • | VO4/18DL-7 | --- | --- | HDB009 | 32310.A |
| | • | HO4/01DL-10 | HDB013 | 33020.A | HDB018 | 33117.A |
| OH 1634 | | | | | | |
| | • | VL4/10D-7 | --- | --- | HDB009 | 32310.A |
| | • | VO4/18DL-7 | --- | --- | HDB009 | 32310.A |
| | • | HO4/01DL-10 | HDB013 | 33020.A | HDB018 | 33117.A |
| Tourismo MBT- 0340- | | | | | | |
| Tourismo MBT- 0340- | • | HO4/01DL-10 | HDB013 | 33020.A | HDB018 | 33117.A |

RVI

| | | | | | | |
|-----------------|---|-------|--------|---------|--------|---------|
| ER 100-2 | | | | | | |
| | • | RI6A | HDB022 | 33213.A | --- | --- |
| GX 187 | | | | | | |
| | • | RI6A | HDB022 | 33213.A | --- | --- |
| MEGABUS | | | | | | |
| | • | RI6A | HDB022 | 33213.A | --- | --- |
| PGC 191 | | | | | | |
| | • | E5A | HDB022 | 33213.A | --- | --- |
| PGC 231 | | | | | | |
| | • | E5A | HDB022 | 33213.A | --- | --- |
| PR 10 | | | | | | |
| | • | E5A | HDB022 | 33213.A | --- | --- |
| PR 100-2 | | | | | | |
| | • | RI6A | HDB022 | 33213.A | --- | --- |
| PR 12 | | | | | | |
| | • | E5A | HDB022 | 33213.A | --- | --- |
| PR 14 | | | | | | |
| | • | E5A | HDB022 | 33213.A | --- | --- |
| PR 180 | | | | | | |
| | • | RI6A | HDB022 | 33213.A | --- | --- |
| PR 8C | | | | | | |
| | • | E5A | HDB022 | 33213.A | --- | --- |
| | • | E5A | HDB022 | 33213.A | --- | --- |
| PR 8C | • | P1140 | HDB001 | 32019.A | HDB018 | 33117.A |

SCANIA

| | | | | | | |
|-------------------|---|------|--------|---------|--------|---------|
| B 111 | | | | | | |
| | • | R640 | HDB012 | 32216.A | --- | --- |
| | • | R640 | HDB012 | 32216.A | HDB010 | 33215.A |
| B 86 | | | | | | |
| | • | R640 | HDB012 | 32216.A | --- | --- |
| | • | R640 | HDB012 | 32216.A | HDB010 | 33215.A |
| BF 111 | | | | | | |
| | • | R640 | HDB012 | 32216.A | --- | --- |
| BF 111-CKD | | | | | | |
| | • | R640 | HDB012 | 32216.A | HDB010 | 33215.A |
| BF 86 | | | | | | |
| | • | R640 | HDB012 | 32216.A | --- | --- |

| | | | | | | |
|---------------|---|------|--------|---------|--------|---------|
| | • | R640 | HDB012 | 32216.A | HDB010 | 33215.A |
| BR 86 | | | | | | |
| | • | R640 | HDB012 | 32216.A | --- | --- |
| BR 86 | • | R640 | HDB012 | 32216.A | HDB010 | 33215.A |
| VOLVO | | | | | | |
| B 6 FA | | | | | | |
| B 6 FA | • | --- | HDB007 | 33022.A | --- | --- |